

Publication B1002B

March 2023

B1002: H V Burlingham Ltd (published June 2015)

Amendment & Supplementary Information List 2

ACKNOWLEDGMENT

I

This Amendment list is only possible as a result of the interest shown by those who have kindly fed in comments on the original publication. The Publications Manager looks forward to further comments, and further Amendments will be published when sufficient additional data is to hand. Whenever possible please state the original source of the information you provide.

Entries new to this addenda are shown with a I in the left hand margin, all other entries have appeared in earlier addenda.

Note: vehicles without body nos are shown in registration no order BU 8748* Leyland TS7 5793 C32-4/35 JH Robinson, Oldham (LA) Chassis no may be 5792. Re-registered DDP 749 with Smiths Luxury Coaches, Reading (BE) 5/48, fitted with 1938 Burlingham C(33)F body ex Western SMT, Kilmarnock (AR) from CS 5233-41 batch. CW 6956* Leyland LC1 45157 C25F 8/26 Wright Bros (Burnley) Ltd (LA) 2 Also recorded with Leyland body. (Note correct but shown in wrong section of notes) FS 8578* AEC Regal 4 O642109 B34R 6/34 Scottish Motor Traction, Edinburgh (MN) B118 Delete * FV 399<u>*</u> AJS Pilot 135 C23-7/29 D Roberts, Blackpool (LA) FV 399: Not confirmed as Burlingham body. FV 1666* 662662 C26R 3/31 W Salisbury & Sons Ltd, Blackpool (LA) AEC Regal Delete * FV 1667* **AEC Regal** 662670 C26R 3/31 W Salisbury & Sons Ltd, Blackpool (LA) Delete * FV 2920* AEC Regal 6621380 C32R 9/32 W Salisbury & Sons Ltd, Blackpool (LA) Also guoted as Harrington bodies as it has Harrington features but photographed in location used by Burlingham. (note refers to FV 2896, 2920) HG 5986* Albion PK115 25018C C31F 9/37 Ribblesdale Coachways Ltd, Blackburn (LA) Exhibited at the 1937 Commercial Motor Show. MJ 7168* Commer C--F c6/35 Unknown operator (ST) Confirmed as MJ 7768. Passed to JE Vessey, Hibaldstow (LI) 4/41. RN 7794* Leyland TD4 7918 L27/26R 3/36 Ribble MS, Preston (LA) 1588 RN 7795* Leyland TD4 7919 L27/26R 3/36 Ribble MS, Preston (LA) 1589 RN 7796* Leyland TD4 7920 L27/26R 3/36 Ribble MS, Preston (LA) 1590 RN 7797* Leyland TD4 3/36 Ribble MS, Preston (LA) 1591 9022 L27/26R 3/36 Ribble MS, Preston (LA) 1592 RN 7798* Leyland TD4 9023 L27/26R 3/36 Ribble MS, Preston (LA) 1593 RN 7799* Leyland TD4 9024 L27/26R RN 7800* Leyland TD4 3/36 Ribble MS, Preston (LA) 1594 9025 L27/26R RN 7801* Leyland TD4 9026 L27/26R 3/36 Ribble MS, Preston (LA) 1595 RN 7802* Leyland TD4 9027 L27/26R 3/36 Ribble MS, Preston (LA) 1596 RN 7794-802 Rebodied Burlingham H30/26R (in batch 2691-2758) 1947. Delete the 1936 bodies, they were Leyland L27/26R. RN 8612 Leyland TD5 301381 L27/26R 9/39 Ribble MS, Preston (LA) 2047 RN 8616 Leyland TD5 301386 L27/26R 2/39 Ribble MS, Preston (LA) 2051 2/39 Ribble MS, Preston (LA) 2053 RN 8618 Levland TD5 301391 L27/26R RN 8619 Leyland TD5 301392 L27/26R 2/39 Ribble MS, Preston (LA) 2054 TF 869* Leyland TS2 60868 B34F by5/45 Grange Motor & Cycle Co Ltd, Grange-over-Sands (LA) Rebody, chassis new 1930. TF 870* Leyland TS2 60869 B34F by5/45 Grange Motor & Cycle Co Ltd, Grange-over-Sands (LA) Rebody, chassis new 1930. AEC Regal UB 6619 662642 C28-5/31 Burton Bros, Leeds (WR) TSM B39A7 UP 8061 8656 B37F 7/33 JJ Baker {G & B Motor Services}, Quarrington Hill (DM) VT 9766 **TSM B10A2** 8655 C32R 8/33 J Hawthorn, Stole-on-Trent (ST) WG 7258* Leyland LZ2A 200727 C35F 6/38 W Alexander, Falkirk (SN) K26 Rebuilt to FC35F 1952.

B1002B/2

	WG 7259*	* Leyland LZ2A 200728 C35F 6/38 W Alexander, Falkirk (SN) K27	
		not WG 7258). Rebuilt to FC35F 1952.	
		* Leyland LZ2A 200730 C35F 6/38 W Alexander, Falkirk (SN) K29	
		Delete *	
	WN 5271 <u>*</u>	<u>*</u> Leyland LT5 <u>2256</u> B32- 2/33 Swansea Bus Services Ltd, Muml	oles (GG)
		Delete as having a Burlingham body when new - it was Leyland. Possibly a 1944 r	ebody for
		United Welsh, Swansea (GG) 685.	
	WS 4794*	* Bedford WTL 871942 <u>C24R</u> 7/35 W Herd, Edinburgh (MN)	
		In the early 1950s chassis no 871942 was quoted for MJ 9818 which was a Bedford	WTL 683101
		Grose C26R body, new to G Hodge, Sandhurst (BE) 2/36. By the early 1950s it wa	s carrying a
		Burlingham CR body of mid-1930s design. Perhaps this was really WS 4794?	
	ABU 446	Bedford WTB 111582 C25F 7/37 R Renton Ltd, Hollinwood (LA)	
1		<u>Delete – body by Plaxton, not Burlingham.</u>	
	AHU 450	Thornycroft Cygnet 24156 C32R 3/34 Bristol Co-operative Society Ltd (GL) 1
		Omitted in error – Burlingham body not Grose.	
	AHU 451	Thornycroft Cygnet 24155 C32R 3/34 Bristol Co-operative Society Ltd (GL) 2
		<u>Omitted in error – Burlingham body not Grose.</u>	
	AKC 601	Rebody, chassis new 1935. Second-hand body fitted 1949, origin unknown.	
		This note appears in error. The origin was known and is shown on page 50 under F	<u>RN 8699-707.</u>
		Bedford WLB f/c 109442 C20F 5/34 W Gilmore, Seaton (CU)	
	BHP 48 <u>*</u>	AEC Regal 6621802 C32F 1/36 R Bolton {Red Horse Coaches}, C	Coventry (WK)
		Rebodied Burlingham (3699) C33F 1949.	
	BHW 642	P. AEC Regal 6621719 C32F 8/35 Binding & Payne Ltd {The Dorothy	y}, Clevedon (SO)
		<u>Delete – body is Petty C32R.</u>	
	CAT 647*	* Dennis Lancet 171093 C32F -/36 DW Burn {Grey De Luxe Coaches	
		Possibly Dennis body, not Burlingham. Re-registered LMX 221 with Valliant Direct	
		Ltd, London W5 (LN) 2/46. Vehicle entry appears on page 46 – it should appear on	<u>page 42.</u>
		Bedford WTB 112333 C25F <u>5/38</u> H Crosthwaite, Frizington (CU)	
	DFS 522	Leyland LZ5 201568 C(33)F 10/39 J Wilkinson, Edinburgh (dealer)	
		New as a brewery lorry, supplied by Wilkinson to Scottish & Newcastle Breweries.	
		by Smith's Luxury Coaches Ltd, Reading (BE) 5/49, with 1938 Burlingham C(33)F b	ody ex Western
		SMT, Kilmarnock (AR) from CS 5233-41 batch.	
	DFS 523	Leyland LZ5 201569 C(33)F 10/39 J Wilkinson, Edinburgh (dealer)	
		New as a brewery lorry. Delete – not recorded with a Burlingham body – or even as	
	EDK 726*	* Leyland TS11 307624 C33F 3/47 Yelloway Motor Services Ltd, Roc	hdale (LA)
		Rebody, chassis new 1942.	
	EEL 46*		
		EEL 46/8, 51/3 Re-registered TAC 480, 478, 796, 477 with Lefkaritis Bros Ltd, Lar	naca (O-CY) 1/57.
		EEL 46 re-registered EEL 46 with JB Dorey, Spilsby, for preservation, 4/84.	
	FTU 757 <u>*</u>	AEC Regal 6622371 C32- 6/39 NS Juckes, Altrincham (CH)	
1		Re-registered ? 1303583, -/, with War Department (Army) (GOV); further re-registered	ered 50 YP 23, -/49.
	HFC 548*	* Leyland LZ2A 201313 C32F 3/39 South Midland, Oxford (OX) 26	
		Body transferred to MYA 217 with G Alford & Sons, Coleford (SO) 6/50.	
	HUP 801	Maudslay Marathon III 70111 B35F 1/48 Gillett Bros (Motor Services) Ltd,	Quarrington Hill (DM)
		23	
	KAH 185*	* Leyland LT5A 4583 C33F 7/49 L Votier {Mascot Coaches}, Norw	
		Rebody, chassis new 1934 registered JO 9057. Body was second-hand, origin unk	nown, possibly rebuilt
1	MYA 217*	* Albion CX39N 60314L C33F 6/50 G Alford & Sons, Coleford (SO)	
		Rebody, chassis new 1939 registered HFC 548.	
i		Leyland PS2/3spl 501244 FC37F 4/51 R & L Jacobs, Barking (EX)	
	RMX 360*	* Dennis Lancet II 175687 C35F <u>5/49</u> Smith's Luxury Coaches Ltd, Rea	ding (BE)
		Body either second-hand, origin unknown or new 1948. Chassis new 1939.	
	? *	AEC 427 427601 C/29 J Smith & Co (Wigan) Ltd, Wigan	
	?*	AEC 427 427604 C/29 J Smith & Co (Wigan) Ltd, Wigan	(LA)
		One of the two AEC 427 (<u>427601/4</u>) may have been EK 7112.	
	*	AEC Regal 662587 RC—C -/31 Oswald Tillotson Ltd (dealer), Bur	
		Passed to RM Walker {Margaret Saloon}, Liverpool (LA) and registered KF 5469 5/3	<u>31.</u>
2345		Leyland PS1 472391 B35F <u>3/48</u> Western SMT, Kilmarnock (AR)	
2508*	BEH 957	Leyland TS7 6348 L27/26R <u>-/45</u> Potteries MT, Stoke (ST) 57	
		Rebody, chassis new 1935. Previously recorded as rebodied in 1945 but 1946 see	
2846 <u>*</u>	AG 8285		ad (CU)
		Rebody, chassis new 1932.	
2852	GUP 666	Leyland PS1/1 462101 C33F <u>5/47</u> Stanhope Motor Services Ltd, Bis	hop Auckland (DM)

I

1

B1002B/3

2854	HTE 538	Leyland PS1/1	470863	C33E	7/47	L9 R Hunt & Sons, Bickerstaff <u>e</u> (LA)		
3082	DHS 19	Leyland PS1/1	462128			J Smith, Barrhead (RW) 15		
3146	CTY 457	Leyland PS1/1	472320			HW Hunter & Sons, Seaton Delaval (ND) 16		
3228	JPT 24	Leyland PS1/1	472996			Graham & Waddington {Primrose Coaches}, Blaydon		
00	••••				<u></u>	(DM)		
3287	KTC 652	Maudslay Marathon III	70362	C33F	2/49	Wilson and Sons, Failsworth (LA)		
		Shown correctly						
3287	EWJ 659		1938. <u>Th</u>	is note is	incorrec	t, body no should read 3826.		
3374*	CNE 801	Leyland TS7		C33F		J Davies, Leigh (LA) 8		
		Rebody, chassis new	1936. <u>(N</u>	ote showr	n but on	page 158 and without body no)		
3376*	GJW 139		44/0/48			Moores Motor Services (Wombourne) Ltd (ST)		
		Rebuilt from chassis o				<u>te, donor chassis unknown.</u>		
3433	CAG 439	Leyland <u>PS1/1</u>	473342			Western SMT, Kilmarnock (AR)		
3434	CAG 438		473337			Western SMT, Kilmarnock (AR)		
3435		Leyland PS1/1	473170			Western SMT, Kilmarnock (AR)		
3436	CAG 441		473473			Western SMT, Kilmarnock (AR)		
3437		Leyland PS1/1	473446			Western SMT, Kilmarnock (AR)		
3438		Leyland PS1/1	472889			Western SMT, Kilmarnock (AR)		
3439		Leyland PS1/1	480687			Western SMT, Kilmarnock (AR)		
3440		Leyland PS1/1	472679 473462			Western SMT, Kilmarnock (AR)		
3441 3442		Leyland <u>PS1/1</u> Leyland <u>PS1/1</u>	473462 480763			Western SMT, Kilmarnock (AR) Western SMT, Kilmarnock (AR)		
3442 3443		Leyland PS1/1	480703			Western SMT, Kilmarnock (AR)		
3444	CAG 447 CAG 448		481209			Western SMT, Kilmarnock (AR)		
3445*	CAG 451	Leyland <u>PS1/1</u>	481726			Western SMT, Kilmarnock (AR)		
0110	0/10 401	Not body no. 3439 as			0/40			
3446	CAG 450	Leyland PS1/1	481725		7/48	Western SMT, Kilmarnock (AR)		
3447	CAG 449		481724			Western SMT, Kilmarnock (AR)		
3448	CAG 455	Leyland PS1/1	481577			Western SMT, Kilmarnock (AR)		
3449	CAG 456	Leyland PS1/1	481578			Western SMT, Kilmarnock (AR)		
3450	CAG 457		481538	C33F		Western SMT, Kilmarnock (AR)		
3582*	KTC 661	Foden PVSC6	28702		3/49	J & JW Fairclough, Lostock (LA)		
		Not 3309 as previously						
3584		Leyland <u>PS1</u>	493303			A & C Wigmore Ltd, Dinnington (WR)		
3678	KPT 72	Dennis Lancet III	569J3	C33F	<u>3/49</u>	R & ML Bissett {Primrose Coaches}, Ryton-on-Tyne		
		• • • · · · · ·				(DM)		
3702 <u>*</u>	HUP 777		33240M	C33F	1/49	Bluebird Coaches (Middlesbrough) Ltd (NR)		
0770*		Corrected from body n		DOOF	(40			
3772*	PJ 2659*	Dennis Lancet (AEC)				Meadowfield Motor Co {Cosy Coaches} (DM)		
						ed and transferred to AEC Regent GKA 278 with		
2790	JPT 737	JJ Baker Ltd {G & B M AEC Regal III 68	821A143			Gillett Bros (Motor Services) Ltd, Quarrington Hill (DM)		
3789	JF1 / 3/	AEC Regarill 60	DZ IA 143	DOOL	<u>9/40</u>	24		
3790*	BWY 182	Leyland TS7	12822	C33F	c-/48	A & C Wigmore Ltd, Dinnington (WR)		
0700	BW1 102					page 158 and without body no)		
3826*	EWJ 659		623007			JW Kitchin & Sons, Pudsey (WR)		
0020						ed with body no 3827 which is HTX 626.		
						ngham records erroneously show 3826/7 for Kitchin		
		and 3827 for Jones.				5		
3831	KTJ 481	Leyland <u>PS1</u>	493299	B35F	10/49	J Fishwick & Sons, Leyland (LA) 34		
3832	KTJ 482	Leyland PS1	493300	B35F	10/49	J Fishwick & Sons, Leyland (LA) 24		
4103	KNE 674	Leyland <u>PS1</u>	493296	C35F	1/50	North Manchester Motor Coaches Ltd (LA)		
4161	KUP 136	Leyland <u>PS1/1</u>	493162	C33F	8/49	T Wilkinson, Sedgefield (DM) 36		
4177-4180 New bodies on H&H Motorways Maudslay Marathon III								
Bodies 4177-4180 were fitted to the following three four vehicles in unknown order plus an unknown vehicle								
		Maudslay Marathon III				H & H Motorways Ltd {Bunty Coachways}, Luton (BD)		
		Maudslay Marathon III				H & H Motorways Ltd (Bunty Coachways), Luton (BD)		
		Maudslay Marathon III				H & H Motorways Ltd (Bunty Coachways), Luton (BD)		
	GIVIJ 3/ /	Maudslay Marathon III	10448	- 000 F	0/49	H & H Motorways Ltd {Bunty Coachways}, Luton (BD)		
4185	KUP 664	AEC Regal III 68	321A492	DP35F	12/49	Gillett Bros (Motor Services) Ltd, Quarrington Hill (DM)		
				2.001	<u>, +</u> J	25		

B1002B/4

4259 JTX 978 Leyland PS2/5 493026 6/50 WH John (Coity Motors), Coity (GG) 4290 CRN 983 Leyland PS2/5 493028 B35F 3/50 Ribble MS, Preston (LA) 2783 4291* CRN 983 Leyland PS2/5 493029 B35F 3/50 Ribble MS, Preston (LA) 2784 4405 AEG 287 Leyland PS1/1 493020 C33F 3/50 Eshaw, Maxey (SP) 4415 GAW 677 Leyland PS1/1 496417 FC35F 3/50 Eshaw, Maxey (SP) Rebodied Platxin (S26253) CG3F with N & S Coaches Ltd, Librowrin (LE) Rebodied Platxin (S26253) CG3F with N & S Coaches Ltd, Librowrin (LE) 451 LPY and PS2/3 496571 C33F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) 451 Leyland PS2/3sp] 501246 CG3F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) 4602 LUP 13 Leyland PS2/3sp] 501242 C37F 9/50 Jiveson & Son, Esh Winning (DM) 4603 ENL 4 Leyland PS2/3sp] 501242 C37F 9/50							
Re-registered CRN 984 cr/83. 4291* CRN 984 Leyland PS2/5 493029 B35F 3/50 Ribble MS, Preston (LA) 2784 4405 AEG 287 Leyland PS11 493302 C33F 3/50 E Shaw, Maxey (SP) 4415 GAW 677 Leyland PS11 496417 CS5F 3/50 T Shitle & Sons, Highley (SH) 4450 GAY 590 Leyland PS11 500028 FC35F 6/50 N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (Sp253) FC33F 6/150 N & S Coaches Ltd, Leicester (LE) //59. 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) 4522 KAD 542 Leyland PS2/3 1495712 C33F 6/50 Strearmways Ld, Penath (GG) Not Brush body - this corrects BB281. Not brush body - this corrects BB281. Not brush body - this corrects BB281. Not Son Son. Esh Winning (DM) 4602 LP13 Leyland PS2/35p] 501242 C37F 9/50 GW wells (Links May (WI) 6/4 4604 HDK 601 Leyland PS2/7							
4291* CRN 984 Leylarid PS2/5 433029 B35F 3/50 Ribble MS, Preston (LA) 2784 4405 AEG 287 Leyland PS11 493302 C33F 3/50 E Shaw, Maxey (SP) 4415 GAW 677 Leyland PS11 496302 C33F 3/50 S Na & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (592653) FC35F 6/50 N & S Coaches Ltd, Leicoster (LE) 7/59. Na Maddington (Primose Coaches), Blaydon (DM) 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Grahama & Waddington (Primose Coaches), Blaydon (DM) 4542 KAO 542 Leyland PS2/3 495712 C33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4551 LNF 553 Leyland PS2/3 501245 FC37F 9/50 J Vreson & Son, Esh Vinning (DM) 4602 LUP 13 Leyland PS2/3 501242 C37F 9/50 J Vreson & Son, Esh Vinning (DM) 4603 FNL 47 Leyland PS2/3 501242 C37F 1/50 GW works exvices Ltd, Rochdale (LA) 4604 HDK 802 Leyland PS2/3 501245 FC37F 1/51 New Kols Links MS), Biyth (ND)	4290*	CRN 983			B35F	3/50	Ribble MS, Preston (LA) 2783
Re-registered CRN 983 c12/82, NSU 250 with Richardson, Helston (CD) 5/89. 4405 AEG 287 Leyland PS1/1 496417 FC35F 3/50 JT Whitle & Sons, Highley (SH) 4415 GAW 570 Leyland PS1/1 500028 FC35F 6/50 N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (SP253) FC35F 6/50 N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (SP253) FC35F 150 Noth Road Engineers (Manchester) Ltd, Oldham (LA) 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 STraham & Waddington (Primrose Coaches), Blaydon (DM) 4542 KAO 542 Leyland PS2/3pl 501246 FC33F 3/51 Noth Road Engineers (Manchester) Ltd, Oldham (LA) 4601 Leyland PS2/1 495112 C33F 9/50 Streamways Ltd, Penath (GG) Not Brush body - this corrects BE281. Not body no 4601 as shown. (GG) HOR Holdman ES2/7 4602 Leyland PS2/3pl 501242 C37F 9/50 GW wells (Links MS), Blyth (ND) 4603 Extra and PS2/3pl 500454 FC37F 1/50 Morer t& Wells Ltd, Anch			Re-registered CRN 984	<u>c7/83.</u>			
4405 AEG 287 Leyland PS1/1 496417 FC35F 3/50 E Shaw, Maxey (SP) 4415 GAW 677 Leyland PS1/1 500028 FC35F 6/50 N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (592633) FC35F 6/50 N & S Coaches Ltd, Leicester (LE) 7/59. 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Ershaw, Maxey (SP) 4542 KAO 542 Leyland PS2/3 4965712 C33F 3/50 Ershaw, Maxey (SP) 4541 LPT 108 Leyland PS2/3 4965712 C33F 3/50 Ershaw, Maxey (SP) 4542 KAO 542 Leyland PS2/3 501246 FC33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4601 KAD 563 Leyland PS2/1 4965712 C33F 3/50 Streamways Ltd, Penarth (G) Not Brush body - this corrects BB281. Not body no 4601 as shown. 600 Schway Motor Services Ltd, Rochale (LA) 4603 EV147 Leyland PS2/15 501245 C37F 2/51 Yelloway Motor Services Ltd, Rochale (LA) 4616 GMW 811 Leyland PS2/15 501265 FC37F 1/51 </td <td>4291*</td> <td>CRN 984</td> <td>Leyland PS2/5 49</td> <td>93029</td> <td>B35F</td> <td>3/50</td> <td>Ribble MS, Preston (LA) 2784</td>	4291*	CRN 984	Leyland PS2/5 49	93029	B35F	3/50	Ribble MS, Preston (LA) 2784
4415 GAW 677 Leyland PS1/1 496417 FC35F 3/50 TWhittle & Sons, Highley (SH) 4450 GAY 590 Leyland PS1/1 500028 FC35F 6/50 N & S Coaches Ltd, Leicester (LE) 7/59. 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) 452 KAO 542 Leyland PS2/31 601246 FC33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4611 KAD 856 Leyland PS2/31 495712 C35F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4611 KAD 856 Leyland PS2/350 501242 C37F 9/50 Wesson & Son, Esh Winning (DM) 4603 ENL 147 Leyland PS2/350 501243 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4606 HDK 801 Leyland PS2/75 501245 FC37F 1/51 A & C Wigmore Ltd, Dinnington (WR) 4620 KWT 71 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621<			Re-registered CRN 983	c12/82,	NSU 250 v	with Ri	chardson, Helston (CO) 5/89.
 4415 GAW 677 Leyland PS1/1 496417 FC35F <u>3/50</u> J Whittle & Sons, Highley (SH) 4450 GAY 590 Leyland PS1/1 50028 FC35F <u>3/50</u> N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (592633) FC35F with N & S Coaches Ltd, Leicester (LE) 7/59. 4471 LPT 108 Leyland PS2/3 496571 C33F <u>3/50</u> Graham & Waddington (Primrose Coaches), Blaydon (DM) 4542 KAO 542 Leyland PS2/31 495712 C35F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4611 KAD 856 Leyland PS1/1 496418 C33F 6/50 Streamways Ltd, Penarth (GG) Not Brush body - this corrects BB281. Not body no 4601 as shown. 4602 LUP 13 Leyland PS2/32pj 501242 C37F 9/50 J Iveson & Son, Esh Winning (DM) 4603 ENL 147 Leyland PS2/32pj 501242 C37F 9/50 J Weson & Son, Esh Winning (DM) 4603 ENL 147 Leyland PS2/32pj 501242 C37F 9/50 J Weson & Son, Esh (Anchale (LA) 4616 GMW 811 Leyland PS2/21 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochale (LA) 4616 GMW 811 Leyland PS2/27 501252 FC37F 10/50 Burrett & Wells (Link Sham (WI) 26 4620 KWT 71 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/7 501265 FC37F 1/51 W Hayes inr, Walsall (ST) 14 4631 EBN 957 Leyland PS2/1 501265 FC37F 1/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4632 MS 124 Leyland PS2/1 501265 FC37F 1/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4634 BBG 1 Leyland PS2/13 501265 FC37F 4/51 Hadrings (Wirrd) Ltd, Birkenhead (CH) 32 4676 BU 334 Leyland PS2/11 500389 FC37F 5/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4687 BBG 1 Leyland PS2/13 501265 FC37F 4/52 Hardings (Wirrd) Ltd, Birkenhead (CH) 32 4867 GBU 334 Leyland PS2/11 510076 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8600 Leyland PS1/11 510076 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8600 Leyland PS1/11 510076 C39C 6/51 Gibson Bros, Barlestone (LA) 4927 XR72 Leyland PS1/11 510076 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4	4405	AEG 287					
 GAY 590 Leyland PS1/1 500028 FC35F it is N & S Coaches Ltd, Kibworth (LE) Rebodied Plaxton (592653) FC35F with N & S Coaches Ltd, Kibworth (LE) 759. H471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) KAO 542 Leyland PS2/1 495712 C35F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) H551 LNF 553 Leyland PS2/1 495712 C35F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) H612 KAO 542 Leyland PS2/3 501242 C37F 9/50 J Iveson & Son, Esh Winning (DM) H613 ENL 47 Leyland PS2/3 501242 C37F 9/50 J Weson & Son, Esh Winning (DM) H614 Leyland PS2/3 501242 C37F 9/50 J Weson & Son, Esh Winning (DM) H616 GMW 11 Leyland PS2/3 501242 C37F 9/50 G W Wells (Links MS), Blyth (ND) H058 102 Leyland PS2/1 501243 FC37F 9/50 G W Wells (Links MS), Blyth (ND) H058 102 Leyland PS2/7 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) H058 102 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) H627 JHO 64 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) H628 WW 71 Leyland PS2/7 501265 FC37F 1/51 W Hayes jnr, Walsall (ST) 14 H631 EBV 57 Leyland PS2/1 501265 FC37F 1/51 Barnes Notor Coaches Ltd, Streamline), Bolton (LA) H632 MTJ 421 Leyland PS2/1 500386 FC37F 5/51 Binsn Kotor Coaches Ltd, Streamline), Bolton (LA) H634 BBG 1 Leyland PS2/1 500386 FC37F 5/51 Binsn Kotor Coaches Ltd, Streamline), Bolton (LA) H635 BB 400 Leyland PS2/1 500386 FC37F 6/51 B Barnes & Sons Ltd, Rawtenstall (LA) H634 BBG 1 Leyland PS2/1 500386 FC37F 6/51 Binsn Kotor Coaches Ltd, Brawtenstall (LA) H634 BBG 1 Leyland PS2/1 500386 FC37F 6/51 Binsn Kotor Coaches Ltd, Brawtenstall (LA) H635 BB 400 Leyland PS2/1 500386 FC37F 6/51 Binsn Kotor Coaches Ltd, Brawtenstall (LA) H634 BB 1 Leyland PS2/1 500386 FC37F 6/51 Binsn Kotor Coaches Ltd, Brawtenstall (LA) H635 C0 Exhand PSU1/11 5100	4415	GAW 677		96417	FC35F		
Rebodied Plaxton (59263): FC35F with N & S Coaches Ltd. Leisster. (LE) 7/99. 4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Graham & Waddington (Primrose Coaches), Blaydon (DM) 4542 KAO 542 Leyland PS2/3pl 501246 FC33F -/51 SH Brownrigg, Egremont (CU) 4551 LNF 553 Leyland PS2/1 495712 C35F 3/50 Stramways Ltd., Penarth (GG) 4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 Stramways Ltd., Penarth (GG) 4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 GW vells (Links MS), Blyth (ND) 4603 ENL 147 Leyland PS2/3spl 501242 C37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4606 HDK 801 Leyland PS2/7 501261 D737F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4620 KWT 71 Leyland PS2/7 501285 FC37F 1/5 W Alner (Victory MS), Fordingbridge (HA) 4621 KWT 72 Leyland PS2/7 501286 FC37F 5/51 B Saream							
4471 LPT 108 Leyland PS2/3 496571 C33F 3/50 Graham & Waddington {Primrose Coaches}, Blaydon (DM) 4542 KAO 542 Leyland PS2/1 495712 C33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4691± KAD 586 Leyland PS1/1 495712 C33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4601 LUP 13 Leyland PS2/14 495712 C33F 3/51 Not Brush body - this corrects B2821. Not body no 4601 as shown. 4602 LUP 13 Leyland PS2/3spl 501242 C37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4603 ENL 147 Leyland PS2/15 501245 FC37F 1/51 Velloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/7 501261 D737F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 71 Leyland PS2/7 501247 D737F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4623 BG Leyland PS2/7 501245 FC37F 5/51 Bins Motor Coaches Ltd (Streamline), Bolton							
(DM) 4542 KAO 542 Leyland PS2/3spl 501246 FC33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4691± KAD 856 Leyland PS1/1 496418 C33F 6/50 Streamways Ltd, Penarth (GG) 4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 J treson & Son, Esh Winning (DM) 4603 ENL147 Leyland PS2/3spl 501242 C37F 9/50 GW wells (Links MS), Blyth (ND) 4607 HDK 801 Leyland PS2/11 500444 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/7 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4620 KWT 71 Leyland PS2/7 501261 D737F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/7 501265 FC37F 1/51 AW Alner (Victory MS), Fordingbridge (HA) 4628 ODH 360 Leyland PS2/11 500388 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (CA) <tr< td=""><td>4471</td><td>LPT 108</td><td></td><td></td><td></td><td></td><td></td></tr<>	4471	LPT 108					
4542 KAO 542 Leyland PS2/3spl 501246 FC33F ./51 North Road Engineers (Manchester) Ltd, Oldham (LA) 46011 KAD 856 Leyland PS1/1 496418 C33F 6/50 Streamways Ltd, Penarth (GG) Not Brush body - this corrects BB281. Not body no 4601 as shown. Machaeta Streamways Ltd, Penarth (GG) 4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 GW wells (Links MS), Blyth (ND) 4603 ENL 147 Leyland PS2/3spl 501242 C37F 9/50 GW wells (Links MS), Blyth (ND) 4604 HOK 801 Leyland PS2/3spl 501242 C37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 71 Leyland PS2/1 501265 FC37F 5/51 Binns Motor Coaches Ltd (Streamline), Bolton (LA) 4628 OD1360 Leyland PS2/11 500389 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4634 B61 Leyland PS2						<u></u>	
4551 LNF 553 Leyland PS2/1 495712 C33F 3/51 North Road Engineers (Manchester) Ltd, Oldham (LA) 4601* KAD 856 Leyland PS1/1 496418 C33F 6/50 Streamways Ltd, Penarth (GG) 4602 LUP 13 Leyland PS2/3spl 501243 FC37F 9/50 J lveson & Son, Esh Winning (DM) 4603 ENL 147 Leyland PS2/3spl 501243 FC37F 9/50 GW wells (Links MS), Blyth (ND) 4604 HDK 801 Leyland PS2/3spl 500424 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 HV 64 Leyland PS2/7 501243 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4628 ODH 360 Leyland PS2/7 501245 FC37F 5/51 B Barnes & Sons Ltd, Ravtenstall (LA) 4631 EBS 97 Leyland PS2/11 500388 FC37F 5/51 B Barnes & Sons Ltd, Ravtenstall (LA) 4634 BSG 1	4542	KAO 542	Levland PS2/3spl 5	01246	EC33E	-/51	
4601* KAD 856 Leyland PS1/1 496418 C33F 6/50 Streamways Ltd, Penarth (GG) Mot Brush body - this corrects B2231. Not body no 4601 as shown. 4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 GW Wells (Links MS), Blyth (ND) 4603 ENL 147 Leyland PS2/3spl 501243 FC37F 9/50 GW Wells (Links MS), Blyth (ND) 4604 HDK 801 Leyland PS2/17 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4608 HDK 801 Leyland PS2/17 501252 FC37F 1/50 Burrett & Wells Ltd, Melksham (WI) 26 4621 KWT 71 Leyland PS2/17 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/17 500388 C37F 1/51 AW Alner (Victory MS), Fordingbridge (HA) 4628 ODH 360 Leyland PS2/11 500386 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4631 EBN 957 Leyland PS2/11 500386 FC37F 5/51 B Barnes & Sons Ltd							
Not Brush body : this corrects BB281. Not body no 4601 as shown.4602LUP 13Leyland PS2/3spl501242C37F9/50J Iveson & Son, Esh Winning (DM)4603ENL 147Leyland PS2/3spl501243FC37F9/50GW Wells (Links MS), Blyth (ND)4603FNL 802Leyland PS2/1500424FC37F2/51Yelloway Motor Services Ltd, Rochdale (LA)4608HDK 802Leyland PS2/7501252FC37F2/51Yelloway Motor Services Ltd, Rochdale (LA)4616GMW 811Leyland PS2/7501261DP37F4/51A & C Wigmore Ltd, Dinnington (WR)4621KWT 71Leyland PS2/7501261DP37F4/51A & C Wigmore Ltd, Dinnington (WR)4622JHO 64Leyland PS2/7501265FC37F3/51W Hayes jnr, Walsall (ST) 144631EBN 957Leyland PS2/11500386FC37F5/51B Barnes & Sons Ltd, Rawtenstall (LA)4632MTJ 421Leyland PS2/11500386FC37F5/51B Barnes & Sons Ltd, Rawtenstall (LA)4633BBG 1Leyland PS2/11500386FC37F5/51B Barnes & Sons Ltd, Rawtenstall (LA)4634BBG 1Leyland PS2/11510079C39C7/51Holts of Oldnam Ltd (LA)4635BB 8500Leyland PSU1/11510079C39C6/51Gibson Bros, Barlestone (LE) 314783BBG 0Leyland PSU1/11510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4874XR F25Leyland P							- (, , , , , , , , , , , , , , , , , ,
4602 LUP 13 Leyland PS2/3spl 501242 C37F 9/50 J Veson & Son, Esh Winning (DM) 4603 ENL 147 Leyland PS2/11 5001243 FC37F 9/50 GW Wells {Links MS}, Blyth (ND) 4607 HDK 801 Leyland PS2/11 500444 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/7 501252 FC37F 10/50 Burret & Wells Ltd, Melksham (WI) 26 4620 KWT 71 Leyland PS2/7 501241 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4622 JHO 64 Leyland PS2/7 501245 FC37F 1/51 A & C Wigmore Ltd, Dinnington (WR) 4623 BD1 30 Leyland PS2/11 500388 C37F 5/51 Binns Motor Coaches Ltd {Streamline}, Bolton (LA) 4634 BBG 1 Leyland PS2/11 500388 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4867 GBU 834	4001	NAD 000					
4603 ENL 147 Leyland PS2/3spj 501243 FC37F 9/50 GW Wells {Links MS}, Blyth (ND) 4607 HDK 801 Leyland PS2/11 500444 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4608 HDK 802 Leyland PS2/7 501252 FC37F 1/50 Burrett & Wells Ltd, Melksham (WI) 26 4620 KWT 71 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 JHO 64 Leyland PS2/7 501285 FC37F 5/51 Binns Motor Coaches Ltd, Rawtenstall (ST) 14 4631 EBN 957 Leyland PS2/11 500386 FC37F 5/51 Binns Motor Coaches Ltd (Streamline), Bolton (LA) 4632 MTJ 421 Leyland PS2/115 500386 FC37F 5/51 Binns Motor Services Coaches Ltd (Rawtenstall (LA) 4634 BG 1 Leyland PS2/115 500386 FC37F 5/51 Binns Motor Service Co, Campbelton (LA) 4637 GUI 98a Leyland PS2/115 50079 Solo Sarbatsone (LE) 31 1/51 4703 <	4600						
4607 HDK 801 Leyland <u>S2/11</u> 500444 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4608 HDK 802 Leyland <u>S2277</u> 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland <u>S2277</u> 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4620 KWT 71 Leyland <u>S2277</u> 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 JHO 64 Leyland <u>PS277</u> 500388 C37F 1/51 AW Cher (Victory MS), Fordingbridge (HA) 4638 BBY 957 Leyland <u>PS2/11</u> 500386 FC37F 5/51 Bins Motor Coaches Ltd (Streamline), Boton (LA) 4634 BBG 1 Leyland <u>PS2/13A</u> 520145 FC37F 4/52 Hardings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland <u>PS2/11A</u> 500386 FC37F 4/51 Gibson Bros, Barlestone (LE) 31 4873 GUT 988 Leyland PSU1/11 510076 C39C 6/51 Gibson B							• • •
4608 HDK 802 Leyland PS2/7 501252 FC37F 2/51 Yelloway Motor Services Ltd, Rochdale (LA) 4616 GMW 811 Leyland PS2/3spl 500454 FC37F 10/50 Burrett & Wells Ltd, Melksham (WI) 26 4620 KWT 71 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/7 500388 C37F 1/51 A & C Wigmore Ltd, Dinnington (WR) 4628 ODH 360 Leyland PS2/7 500388 C37F 1/51 A Waner (Victory MS), Fordingbridge (HA) 4631 EBN 957 Leyland PS2/11 500386 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4633 BGG 1 Leyland PS2/11 500386 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4634 BG 1 Leyland PS2/11 500386 FC37F 5/51 Holts of Oldham Ltd (LA) 4787 GUT 988 Leyland PS2/11 50076 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 500 Leyland PS1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 <							
4616 GMW 811 Leyland PS2/3spl 500454 FC37F 10/50 Burrett & Wells Ltd, Melksham (WI) 26 4620 KWT 71 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland PS2/7 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 JHO 64 Leyland PS2/7 500388 C37F 1/51 AW Alner (Victory MS), Fordingbridge (HA) 4628 ODH 360 Leyland PS2/11 500388 C37F 5/51 B most Motor Coaches Ltd (Streamline), Bolton (LA) 4634 BBG 1 Leyland PS2/13A 520145 FC37F 5/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4867 GBU 834 Leyland PS2/11 510038 C37F 1/51 Holts of Oldham Ltd (LA) 4873 GUT 988 Leyland PSU1/11 5100524 C39C 6/51 Bioson Bros, Barlestone (LE) 31 4915 S 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 5100757 FC35F 4/54 CW Barlie b							
4620 KWT 71 Leyland <u>BS2/7</u> 501261 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4621 KWT 72 Leyland <u>PS2/7</u> 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 JHO 64 Leyland <u>PS2/7</u> 500388 C37F 1/51 AW Alner {Victory MS}, Fordingbridge (HA) 4628 ODH 360 Leyland <u>PS2/11</u> 500388 C37F 5/51 Binns Motor Coaches Ltd {Streamline}, Bolton (LA) 4634 BB6 1 Leyland <u>PS2/111</u> 500386 FC37F 5/51 Barnes & Sons Ltd, Rawtenstall (LA) 4634 BB6 1 Leyland <u>PS2/111</u> 500386 FC37F 5/51 Hordings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 8497 XR 725 Leyland PSU1/11 52097 F							
4621 KWT 72 Leyland PS2/7 501247 DP37F 4/51 A & C Wigmore Ltd, Dinnington (WR) 4627 JHO 64 Leyland PS2/7 500388 C37F 1/51 AW Alner {Victory MS}, Fordingbridge (HA) 4628 ODH 360 Leyland PS2/3 501265 FC37F 3/51 W Hayes jnr, Walsall (ST) 14 4631 EBN 957 Leyland PS2/11 500386 FC37F 5/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4632 MTJ 421 Leyland PS2/13 520145 FC37F 5/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4636 BBG 1 Leyland PS2/13A 520145 FC37F 4/52 Hardings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland PSU1/15 510534 C39C 7/51 Hoits of Oldham Ltd (LA) 4873 GUT 988 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 510076 C39C 8/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H							
4627 JHO 64 Leyland PS2/7 500388 C37F 1/51 AW Alner {Victory MS}, Fordingbridge (HA) 4628 ODH 360 Leyland PS2/3 501265 FC37F 3/51 W Hayes jnr, Walsall (ST) 14 4631 EBN 957 Leyland PS2/11 500389 FC37F 5/51 Bins Motor Coaches Ltd {Streamline}, Bolton (LA) 4632 MTJ 421 Leyland PS2/11 500386 FC37F 5/51 B Barnes & Sons Ltd, Rawtenstall (LA) 4634 BBG 1 Leyland PS2/11A 500386 FC37F 4/52 Hardings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 50044961) 5762* 549* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN)							
4628ODH 360Leyland $\overline{PS2/3}$ 501265 $\overline{FC37F}$ 3/51W Hayes jnr, Walsall (ST) 144631EBN 957Leyland $\overline{PS2/11}$ 500389 $\overline{FC37F}$ 5/51Binns Motor Coaches Ltd {Streamline}, Bolton (LA)4632MTJ 421Leyland $\overline{PS2/11}$ 500386 $\overline{FC37F}$ 5/51B Barnes & Sons Ltd, Rawtenstall (LA)4634BBG 1Leyland $\overline{PS2/13A}$ 520145 $\overline{FC37F}$ 4/52Hardings (Wirral) Ltd, Birkenhead (CH) 324867GBU 834Leyland $\overline{PSU1/15}$ 510534C39C7/51Holts of Oldham Ltd (LA)4873GUT 988Leyland $\overline{PSU1/11}$ 510079C39C6/51Gibson Bros, Barlestone (LE) 314915SB 8500Leyland $\overline{PSU1/11}$ 510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4927*XRE 725Leyland $\overline{PSU1/11}$ 510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4927*XRE 725Leyland PS1/152016C41C6/52Harper Bros (Heath Hayes) Ltd (ST) 50Rebuilt to DP41F by Harper 1967.(Note shown after body 4961)5499*JXL 452Leyland PS1/1470675FC35F4/54CW Banfield Ltd, London SE17 (LN)Rebody, chassis new 1948.(Note shown after body 54114)Sons Ltd, Pudsey (WR)5761*NWW 806Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)5762*NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54.6055OGA 31 </td <td>4621</td> <td>KWT 72</td> <td>Leyland <u>PS2/7</u> 50</td> <td>01247</td> <td>DP37F</td> <td>4/51</td> <td>A & C Wigmore Ltd, Dinnington (WR)</td>	4621	KWT 72	Leyland <u>PS2/7</u> 50	01247	DP37F	4/51	A & C Wigmore Ltd, Dinnington (WR)
4631EBN 957Leyland PS2/11500389FC37F5/51Binns Motor Coaches Ltd {Streamline}, Bolton (LA)4632MTJ 421Leyland PS2/11500386FC37F5/51B Barnes & Sons Ltd, Rawtenstall (LA)4634BBG 1Leyland PS2/13A520145FC37F4/52Hardings (Wirral) Ltd, Birkenhead (CH) 324867GBU 834Leyland PSU1/15510534C39C7/51Holts of Oldham Ltd (LA)4873GUT 988Leyland PSU1/11510079C39C6/51Gibson Bros, Barlestone (LE) 314915SB 8500Leyland PSU1/11510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4927*XRE 725Leyland PSU1/11520916C41C6/52Harper Bros (Heath Hayes) Ltd (ST) 508ebuilt to DP41F by Harper 1967.(Note shown after body 4961)5499*JXL 452Leyland PS1/1470675FC35F4/54CW Banfield Ltd, London SE17 (LN)8ebody, chassis new 1948.(Note shown after body 5414)5761*NWW 806Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)5762*NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54.6055OGA 31AEC RelianceMU3RV631C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG) </td <td>4627</td> <td>JHO 64</td> <td>Leyland <u>PS2/7</u> 50</td> <td>00388</td> <td>C37F</td> <td>1/51</td> <td>AW Alner {Victory MS}, Fordingbridge (HA)</td>	4627	JHO 64	Leyland <u>PS2/7</u> 50	00388	C37F	1/51	AW Alner {Victory MS}, Fordingbridge (HA)
4632MTJ 421Leyland $\overline{PS2/11}$ 500386FC37F5/51B Barnes & Sons Ltd, Rawtenstall (LA)4634BBG 1Leyland $\overline{PS2/13A}$ 520145FC37F4/52Hardings (Wirral) Ltd, Birkenhead (CH) 324867GBU 834Leyland $\overline{PSU1/11}$ 5100534C39C7/51Holts of Oldham Ltd (LA)4873GUT 988Leyland $\overline{PSU1/11}$ 510079C39C6/51Gibson Bros, Barlestone (LE) 314915SB 8500Leyland $\overline{PSU1/11}$ 510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4927*XRE 725Leyland PSU1/11520916C41C6/52Harper Bros (Heath Hayes) Ltd (ST) 50Rebuilt to DP41F by Harper 1967.(Note shown after body 4961)5499*JXL 452Leyland PS1/1470675FC35F4/54CW Banfield Ltd, London SE17 (LN)Rebody, chassis new 1948.(Note shown after body 5414)5761*NWW 806Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)5762*NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54.6055OGA 31AEC RelianceMU3RV631C41C4/556115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F5/59P Jacobs {Thatched Ho	4628	ODH 360	Leyland PS2/3 50	01265	<u>FC37F</u>	3/51	W Hayes jnr, Walsall (ST) 14
 4634 BBG 1 Leyland PS2/13A 520145 FC37F 4/52 Hardings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland PSU1/15 510534 C39C 7/51 Holts of Oldham Ltd (LA) 4873 GUT 988 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69035 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 	4631	EBN 957	Leyland PS2/11 50	00389	FC37F	5/51	Binns Motor Coaches Ltd {Streamline}, Bolton (LA)
 4634 BBG 1 Leyland PS2/13A 520145 FC37F 4/52 Hardings (Wirral) Ltd, Birkenhead (CH) 32 4867 GBU 834 Leyland PSU1/15 510534 C39C 7/51 Holts of Oldham Ltd (LA) 4873 GUT 988 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69035 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 	4632	MTJ 421	Leyland PS2/11 50	00386	FC37F	5/51	B Barnes & Sons Ltd, Rawtenstall (LA)
 4867 GBU 834 Leyland PSU1/15 510534 C39C 7/51 Holts of Oldham Ltd (LA) 4873 GUT 988 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) 5762* NWW 805 Atkinson PL745H FC2363 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 	4634	BBG 1	Leyland PS2/13A 52	20145	FC37F	4/52	Hardings (Wirral) Ltd, Birkenhead (CH) 32
 4873 GUT 988 Leyland PSU1/11 510079 C39C 6/51 Gibson Bros, Barlestone (LE) 31 4915 SB 8500 Leyland PSU1/11 510076 C39C 8/52 West Coast Motor Service Co, Campbeltown (AL) 4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) 5762* NWW 805 Atkinson PL745H FC2363 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69074 C41F 5/59 R Jacobs (Thatched House Coaches), Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 							
4915SB 8500LeylandESU1/11510076C39C8/52West Coast Motor Service Co, Campbeltown (AL)4927*XRE 725Leyland PSU1/11520916C41C6/52Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961)5499*JXL 452Leyland PS1/1470675FC35F4/54CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414)5761*NWW 806Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54.6055OGA 31AEC RelianceMU3RV631C41C4/55Scottish Co-operative Wholesale Society Ltd, Glasgow (LK)6115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
4927* XRE 725 Leyland PSU1/11 520916 C41C 6/52 Harper Bros (Heath Hayes) Ltd (ST) 50 Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) 5762* NWW 805 Atkinson PL745H FC2363 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69035 C41F 5/59 R Jacobs {Thatched House Coaches},							
Rebuilt to DP41F by Harper 1967. (Note shown after body 4961) 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F <u>11/54</u> JW Kitchin & Sons Ltd, Pudsey (WR) 5762* NWW 805 Atkinson PL745H FC2363 B44F <u>11/54</u> JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service <u>11/54</u> . 6055 OGA 31 AEC Reliance MU3RV631 C41C <u>4/55</u> Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG <u>46033</u> C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG <u>51343</u> C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 <u>PCY 599</u> AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 <u>69035</u> C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 <u>69674</u> C41F 5/59 <u>R Jacobs {Thatched House Coaches}, Barking (EX)</u> 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
 5499* JXL 452 Leyland PS1/1 470675 FC35F 4/54 CW Banfield Ltd, London SE17 (LN) Rebody, chassis new 1948. (Note shown after body 5414) 5761* NWW 806 Atkinson PL745H FC2362 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) 5762* NWW 805 Atkinson PL745H FC2363 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 		/					
Rebody, chassis new 1948. (Note shown after body 5414)5761*NWW 806 Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)5762*NWW 805 Atkinson PL745HFC2363B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)6055OGA 31AEC RelianceMU3RV631C41C4/55Scottish Co-operative Wholesale Society Ltd, Glasgow6115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169074C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle	5499*	.IXI 452					
5761*NWW 806Atkinson PL745HFC2362B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)5762*NWW 805Atkinson PL745HFC2363B44F11/54JW Kitchin & Sons Ltd, Pudsey (WR)6055OGA 31AEC RelianceMU3RV631C41C4/55Scottish Co-operative Wholesale Society Ltd, Glasgow6015TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6115TOB 336Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle	0100	0/12 102					
 5762* NWW 805 Atkinson PL745H FC2363 B44F 11/54 JW Kitchin & Sons Ltd, Pudsey (WR) NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54. 6055 OGA 31 AEC Reliance MU3RV631 C41C 4/55 Scottish Co-operative Wholesale Society Ltd, Glasgow (LK) 6115 TOB 336 Bedford SBG 46033 C41F 3/56 LF Bowen Ltd, Birmingham (WK) 6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle 	5761*	N/W/W 806					
NWW 806, 805: Chassis new 1951, bodied 2/54, delivered 7/54, entered service 11/54.6055OGA 31AEC RelianceMU3RV631C41C4/55Scottish Co-operative Wholesale Society Ltd, Glasgow (LK)6115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
6055OGA 31AEC RelianceMU3RV631C41C4/55Scottish Co-operative Wholesale Society Ltd, Glasgow (LK)6115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle	5702	110000 000					
G115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle	COFF	004 24					
6115TOB 336Bedford SBG46033C41F3/56LF Bowen Ltd, Birmingham (WK)6514TWT 282Bedford SBG51343C41F4/57Longster Brothers Ltd, Pateley Bridge (WR)6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle	6055	UGA 31	AEC Reliance MOSP	(1001	0410	4/33	
6514 TWT 282 Bedford SBG 51343 C41F 4/57 Longster Brothers Ltd, Pateley Bridge (WR) 6556 PCY 599 AEC Reliance MU3RA1070 C41F 9/57 PS Davey, Swansea (GG) 6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle	0445			10000	0445	0/50	
6556PCY 599AEC RelianceMU3RA1070C41F9/57PS Davey, Swansea (GG)6781BCU 913Bedford SB169035C41F5/59Hall Bros (South Shields) Ltd (DM)6847485 NVXBedford SB169674C41F5/59R Jacobs {Thatched House Coaches}, Barking (EX)120/allbody nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
6781 BCU 913 Bedford SB1 69035 C41F 5/59 Hall Bros (South Shields) Ltd (DM) 6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
6847 485 NVX Bedford SB1 69674 C41F 5/59 R Jacobs {Thatched House Coaches}, Barking (EX) 120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
120/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle							
	6847	485 NVX	Bedford SB1	69674	C41F	5/59	R Jacobs {Thatched House Coaches}, Barking (EX)
121/all body nos are in Duple (Northern) series but considered Burlingham by PSV Circle	120/all						
	121/all		body nos are in Duple (N	lortherr	n) series bu	t consi	dered Burlingham by PSV Circle

Any general comments, updates or corrections to B1002 (or any other publication) may be sent to the Publications Manager, PSV Circle, 11th floor Wentworth House, 350 Eastern Avenue ILFORD IG2 6NW. or via email to publications.manager@psv-circle.org.uk